ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
12

Ward Name
Shettihalli

Street ID
W0307, W0230, W0301, W0228, W0309, W0311, W0313, W

Street Name
NA, Bimel Behind Rd, R H B Colcny 1st Main Rd, 11th Crs Lakshmi Sagar Lyt

Significant Landmark
Vinayaka Layout

Segment No.
12/C-W0307/S105740

Total Length (m)
444.23

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	23.23	77.517657	13.071473	77.517855	13.071392	W0301	W0309
2	31.87	77.517908	13.071371	77.518179	13.071258	W0309	W0313
3	59.68	77.517694	13.071494	77.518200	13.071283	W0313	W0315
4	28.12	77.517370	13.071630	77.517608	13.071530	W0315	W0319
5	27.38	77.517361	13.071597	77.517593	13.071499	W0319	W0363
6	29.37	77.517058	13.071722	77.517307	13.071618	W0301	W0307
7	26.34	77.517067	13.071756	77.517290	13.071662	W0307	W0311
8	105.62	77.516082	13.072163	77.516979	13.071791	W0311	W0317
9	112.62	77.516054	13.072134	77.517011	13.071739	W0317	W0363

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to rodas and drains at Vinayakanagar main road and surrounding area in ward no 12 Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2018

Year
2017 - 2018

Type of Work
Others

Other Work Type
Culverts and drains

Tender
Not a Tender

Work Details
Construction of drains and culverts

Job No. / Work Code
012-18-000005

Work Order No.
BBMP/EE/DD/WO/37/2018-19

Work Order Date
11/09/2018

Period of Extention
90 days

Defect Liability Period From
18/01/2019

Defect Liability Period To
18/01/2020

Multiple road involved with the same Job No/ Work Code #
Yes

Scanned by CamScanner

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Technical Manager(West), KRIDL		4996534.00
Phone No.	**E-Mail ID**	
9845009297		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Shiva Kumar
Date of Inspection	**Remarks**	
04/08/2019		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	DODDAIAH	04/08/2019	30/09/2019	
EE	Jayalingappa	04/08/2019	30/09/2019	
AEE	Jayalingappa	04/08/2019	30/09/2019	
AE	Shiva Kumar	04/08/2019	30/09/2019	
AE	Shiva Kumar	03/08/2019	23/02/2019	

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0307, W0230, W0301, W0228,

Scanned by CamScanner